In the Specification

Please replace the paragraph beginning on line 10 of page 10 with the following rewritten paragraph.

The control circuit 18 subdivides the right half of the upper side into several sections [[281 to 284]] 28₁ to 28₄. In the Figure, these sections are separated from each other and from the left-hand half of the upper side by dashed lines, but these lines only serve as an orientation for the viewer; in the real back-short 30, they do no exist. The control circuit 18 recognizes a working frequency of the bask-short from in which of the sections [[281 to 284]] 28₁ to 28₄ the bore 26 is located (section [[283]] 28₃ in the present case).